



CENTRAL SOUTH CARPENTERS TRAINING TRUST
UNITED BROTHERHOOD OF CARPENTERS AND JOINERS OF AMERICA
Arkansas • Louisiana • Oklahoma • Texas

Millwright Tool List – Arkansas and Oklahoma

1st and 2nd Year Apprentices

- 1-Tool box
- 2-Adjustable wrenches 8” & 12”
- 1-Tape Measure 25ft minimum
- 1-Plumb bob
- 1-Chalk box (100’-Retractable)
- 1-Torpedo level magnetized
- 1-Combination wrenches (3/8” to 1 1/4”)
- 1-Complete set 1/2 inch drive sockets up to 1 1/4”
- 2-Ball peen hammers (small and large)
- 1-Set of punches with at least 1 center punch
- 1-Set Cold chisels
- 1-Set of assorted screwdrivers both slotted and Phillips
- 1-Set of Allen Wrenches up to 3/8”
- 1-Punch Bar or Wonder Bar
- 1-Hacksaw
- 1-Pair Slide Cutter Pliers
- 1-Pair Vise Grip Pliers
- 1-Combination Square
- 1-Scraper
- 1-Half Round File (10inch)
- 1-Flat File (10inch)
- 1-Mechanics Mirror
- 1-Magnet Extension
- 1-Hone Stone
- 1-6” Scale with Clip

Journeyman including all previous tools

- 1-12” Precision Level (ex. Starrett #98)
- 1-Outside Micrometer (1” to 2”)
- 1-Small set inside micrometers
- 1-Center Head for Combination Square
- 1-Protractor Head for Combination Square

**3rd and 4th Year Apprentices
additional**

- 1-Outside Micrometer (0 to 1”)
- 1-Set Feeler Gauges
- 1-Steel Scribe
- 1-6” Precision Level (ex. Starrett #98)
- 1-Dial Indicator with attachments (ex. Starrett #196)
- 1-Set adjustable parallels or snap gauges
- 1-Set thread gauges
- 1-Magnetic base holder
- 1-Inside Caliper (6inch)
- 1-Outside Caliper (6inch)
- 1-Set of dividers (6inch)